MARYLAND HISTORICAL TRUST DETERMINATION OF ELIGIBILITY FORM

NR Eligible: yes_____no

Property Name: Barnes Property	Inventory Number: CARP-1678		
Address: 1537 West Liberty Road	City: Sykesville Zip Code: 21784		
County: Carroll	USGS Topographic Map: Winfield		
Owner: Barnes Family Limited Partnership	Is the property being evaluated a district? yes		
Tax Parcel Number: 69 Tax Map Number	:: 67 Tax Account ID Number: 09-000356		
Project: Barnes Property	Agency: Federal Communications Commission		
Site visit by MHT staff: X no yes Name:			
Is the property is located within a historic district?			
1	Name of District: yes no Non-contributing but eligible in another context yes		
If the property is not within a district (or the property is a	a district) Preparer's Recommendation: Eligible X yesno		
Criteria:AB _X C D C	onsiderations: AB C D E FGNone		
Documentation on the property/district is presented in: (No documents were identified)			
Description of Property and Eligibility Determination: (Use continuation sheet if necessary and attach map and photo)		
The property was most recently observed and photographe	d in August 2003.		
There are currently no documents describing or related to	the property located at the Maryland Historical Trust Library.		
to the east of the intersection of West Liberty and Woodbi Maryland. The property consists of a grouping of nine str	Liberty Road (State Route 26), approximately three tenths of a mile ne Road, near the community of Winfield in Carroll County, actures, including the main farmhouse, several garage/storage k barn. An asphalt paved drive leads up to the compound, which is farmhouse.		
rear of the house also has a porch. The plan seems to have constructed over the course of its existence. This also was	porch on the north or front elevation facing West Liberty Road. The to have formerly been a less complex "T" shape, with additions communicated by a resident who indicated she has lived in the house ated that the primary structure was built in 1920, and is approximately		
MARYLAND HISTORICAL TRUST REVIEW			
	ility not recommended		
Criteria:AB \(\times_CD \) Considerations:MHT Comments	AB C D E F GNone		
/ / /			
Janus Las lutts	8/28/03		
Reviewer, Office of Preservation Services	9 9 10 3 Date		
Reviewer, NR Program	Date		

NR-ELIGIBILITY REVIEW FORM

Barnes Property

Page 2

Inventory Number: CARR-1678


The main house is a relatively simple structure that seems Victorian in general appearance; a fact reinforced by the "T" plan, a centrally located steep-sloped gable dormer at the front elevation, and the three-bay porch. The house however does not have much ornamentation beyond the dormer, bracket details, and hand railing. It merely seem to have a discreet, elegant Victorian formalism exemplified by the minimal detail but accurate representation of proportion and scale. Formalistically, the farmhouse shares idiomatic qualities with other domiciles of its nature located in this agricultural region. In particular the plan and general elevation mimic the Andrew P. Frizzel House located within a few miles of the property on Salem Bottom Road. What the house lacks in decoration, it makes up for in simple geometric polish. The severe symmetry of the façades on three sides of the upper portion of the "T" relate a degree of idiosyncrasy with regard to other structures at the property, which are more primitive and functional in shape, and rustic in materials. These buildings are generally utilitarian structures of varying age, shape and materials. One building of note seems mildly distinctive in its asymmetrical gable slope lengths, wall heights, and its parallel low foundation elements perpendicular to the roof overhang, and looking like fins extending out of the ground. This building is the furthest from the road at the back of the compound

While the majority of the structures are nondescript, the bank barn, coupled with the main house, helps generate the distinct identity of the property. The bank barn is a rather large building set apart from the rest of the compound in a generally open area appearing slightly elevated above the other buildings. The quality of scale is expertly manipulated by two principal and defining factors. The first being the siting of the barn: out in the open (with the exception of a single tree on the east side), and at the head of the sloping sod field running to the edge of the highway from the foot of the barn. The second scale factor is the array of fenestrations on all sides of the barn that make it appear larger than it is. The barn is in fact large, but the quantity and relatively small size of the decorative-framed openings with horizontal louver seems to add a few more stories. Other physical traits include the tin roof, the red-painted exterior wood siding, the decorative, toothed fascia trim at eaves, and the stone and concrete masonry unit lower level wall. The barn is reportedly one of very few with the decorative trim work this building possesses. The main level of the barn is actually the second entered from the west. The ground leading into the barn appears to perhaps have been placed fill ramping up to the barn. The lower level is exposed on three sides and entered on two. The superstructure for the barn is timber framing above the stone lower level walls. The barn is currently in use and appears to be in good condition. A painted sign at the top of the north side of the bank barn contains the numbers 1881.

Another structure of interest is the remains of the wood framing for a silo. These ruins do not appear to serve any purpose other than to be reminiscent of its former function. Another silo appears to have been located beside the bank barn. This too is in ruins, although instead of wood framing, it is identified by the concrete circular base partially overgrown with vegetation.

The general setting of the property is rural and agricultural. The topography in the general area of the buildings is relatively flat. The ground slopes slightly up to the barn from the property access road. On the opposite side of the bank barn the ground slopes slightly down to the east away from the compound. Agriculture still extends its presence into the identity of property. The field east of the buildings is sod, access trails extent to grazing fields for cattle, and the barn still houses farm equipment. The community of Winfield near to the west, by its proximity diminishes the degree of its rural character, but not its architectural quality. The property could be considered for eligibility for registration under the terms of Criterion C: Design/Construction.

Prepared by:	William C. Riggs, RA, Histor	oric Archit	Date Prepared:	8/20/2003
7000			1777	



SITE PLAN

NOT TO SCALE



Determination of Eligibility

Barnes Property 1537 West Liberty Road Sykesville, Maryland 21784

CARR-1678




AERIAL PHOTOGRAPH

NOT TO SCALE



Determination of Eligibility
Barnes Property
1537 West Liberty Road
Sykesville, Maryland

CARR- 1678



SITE VICINITY MAP

Winfield, MD Quadrangle (Dated 1979) SCALE: As Shown



Determination of Eligibility

Barnes Property 1537 West Liberty Road Sykesville, Maryland

CARR-1678



BARNES PROPERTY CARROLL CO., MD C. GONZALEZ AUGUST 2003 NEGO MOSHPO FARM HOSE - NORTH ELL. CA+ 1678 1/10

. Phate Gallery, DS II 193



BARNES PREPERTY CARROLL CO, MD CGONZALEL AVOUST 2003 NEGO @ MDSHPO FARMHOUSE - NORTH BUD CARR- 1678 2/10



BAHNES PROPERTY CARROLL CO, MD C. GUNZALEZ AUGUST 2003 NEG-LOC: MDSHPO FARM HOUSE - WEST DEN 3/10 CARR - 1679



BANNES PROPERTY CARROLL CO., MO C. GONZALEZ AVOUST 2003 NET LOC: MOSHPO FARM HUSE - SOUTH CLEV CARR-1678 3 4/10



BARNES PREPERTY CARROCACO, MO C. GONZALEZ AUGUST 2003 NEGO LOC: MD SHPO BANK BARN CARR- 1678 5/10



BARNES PROPERTY CARRULL CO, MO C. GONZALEZ AUGUST 2003 NEG-LOC: MD SHOO BANK BARN CARR- 1678 6/10



BARNES PHOPERTY CAPROLE CO, MD CIGGIZALEL AUGUST 2003 NOS APO BANK BARN-INTERIOR CARP- 1678 7/10

9





BARNES PROPERTY CAPPLOLL CO, MO C GONZALLZ AUGUST 2003 NEG: MD SHPO CARD- 1678 8/10

. Photo Gallery, 66-11/65



BARMES PROPERTY CARROLL CO, NO CAPLOS GONZALEZ AUGUST 2003 NEO: MD SHPO CAPP- 1678 9/10

Photo Gallens: TO 11/83



BARNES PROPORTY
CARROLL-CO., MD
CALLOS GANZAND
AUGUST ZOO3
NEG: MD SHPO
CARR- 1678